



## APPEL D'OFFRE REF 07/001/DLA/2024

**ELIZABETH GLASER PEDIATRIC AIDS FOUNDATION (EGPAF)**

**PROJET DE RECYCLAGE-RECONDITIONNEMENT & DESTRUCTION DU MATERIEL INFORMATIQUE ET  
COMMUNICATIONS DECLASSE PAR EGPAF CAMEROON**

**DATE LIMITE DE RECEPTION DES OFFRES: 07 AOUT 2024, 17H00 HEURES DU CAMEROUN**

### **SOMMAIRE :**

- I-      *MODALITES PRATIQUE DE SOUMISSION***
- II-     *PRESENTATION D'EGPAF AU CAMEROUN***
- III-    *CONSTITUTION DU DOSSIER DE CANDIDATURE***
- IV-     *CRITERES D'ATTRIBUTION DU MARCHE***
- V-      *ANALYSE DES OFFRES***
- VI-     *LISTE DES MATERIELS A DECLASSER (EN ANNEXE)***

## I- MODALITES PRATIQUE DE SOUMISSION

Toutes les pièces du dossier de soumission doivent être reliées sur un seul (unique) document et classées suivant l'ordre ci-dessus mentionné avec des séparations entre les différentes grandes rubriques A, B et C.

Ce document sera produit en deux exemplaires (un original et une copie) qui seront scellés dans une enveloppe qui ne devra donner aucune indication sur l'identité du soumissionnaire. En cas de dépôt physique de dossier de candidature ou alors envoyé par mail à l'adresse email suivante : [cameroontenders@pedaids.org](mailto:cameroontenders@pedaids.org)

Y sera mentionner sur l'enveloppe le numéro de l'avis d'appel d'offre et la mention : "**'N'OUVRIR QU'EN SEANCE DE DEPOUILLEMENT'**"

Vous déposerez votre offre avec décharge dans les bureaux d'EGPAF tous les jours ouvrables du Lundi au Jeudi de Chaque semaine Entre 8h et 17heures 30 Minutes et de 08h à 14 heures les vendredis pour la période allant du ceci du 24/07/2024 au 07/08/2024 contre décharge dans un registre qui sera prévue à cet effet.

**NB : Les offres reçues après la date et/ou l'heure butoirs ne seront pas considérées.**

## ***II- PRESENTATION D'EGPAF***

La Fondation Elizabeth Glaser Pediatric AIDS est un leader mondial dans la lutte contre le VIH et le SIDA pédiatrique, travaillant dans 19 pays et sur plus de 5 500 sites à travers le monde pour prévenir la transmission du VIH aux enfants et aider ceux qui sont déjà infectés. Aujourd'hui, grâce au travail très réussi de la Fondation et de ses partenaires, le SIDA pédiatrique a été pratiquement éliminé aux États-Unis. Avec un effectif mondial croissant de plus de 1 000 personnes, dont neuf sur 10 qui travaillent sur le terrain, la mission mondiale de la Fondation est de mettre en œuvre des programmes de prévention, de soins et de traitement du VIH ; faire progresser la recherche innovante ; et d'exécuter des activités de plaidoyer mondiales stratégiques et ciblées pour apporter des changements spectaculaires dans la vie de millions de femmes, d'enfants et de familles dans le monde. Pour plus d'informations, veuillez visiter notre page : [www.pedaids.org](http://www.pedaids.org).

EGPAF travaille en partenariat avec le ministère de la Santé pour soutenir les services de prévention, de soins et de traitement du VIH et de renforcement des systèmes de santé. L'EGPAF est principalement financé par le PEPFAR à travers les Centres for Disease Control and Prevention (CDC) et l'Agence des États-Unis pour le développement international (USAID). ELIZABETH GLASER PEDICATRIC AIDS FOUNDATION Cameroun a pour siège Social Yaoundé et représentée par **Dr Patrice TECHENDJOU**, Directeur Pays demeurant et domicilie au siège de ladite institution, identifie au numéro contribuable **M0914125000911Q** ci-après dénommée EGPAF.

### **III-CONSTITUTION DU DOSSIER DE CANDIDATURE**

Peut faire acte de candidature, toute entreprise spécialisée et expérimentée dans le domaine informatique : le recyclage-reconditionnement & destruction du matériel informatique et communication déclassés par EGPAF .

Les pièces suivantes constitueront l'offre du prestataire :

#### **A- Pièces administratives**

- 1- Une copie de cet avis d'appel à cotation entièrement paraphé sur toutes ses pages et signé à la dernière page par le prestataire ;
- 2- Attestation de non-redevance fiscale (en cours de validité) ;
- 3- Un Plan de localisation du bureau principal du soumissionnaire
- 4- Attestation d'immatriculation ;
- 5- Copie Certifiée Conforme de l'expédition du Registre de commerce (en conformité avec l'objet du présent appel d'offre) ;
- 6- Attestation de domiciliation bancaire ;

#### **B- PIECES TECHNIQUES**

- 1- Présentation de l'entreprise (historique, secteur d'activité, structure organisationnelle du soumissionnaire avec présentation du personnel clé) ;
- 2- Un exposé décrivant de manière explicite la compréhension des besoins exprimés par EGPAF,
- 3- Méthodologie de recyclage dans la cas du réemploi et de destruction en tenant compte du volet environnemental et social du matériel informatique ;
- 4- La liste de toutes les personnes que le soumissionnaire compte faire intervenir dans la réalisation de la mission, ainsi que leurs CVs (Le prestataire indiquera le profil et l'expérience du personnel de la mission) ;
- 5- Des (04) procès verbaux de reception provisoires ou définitives de réalisation des travaux similaires réalisés par le soumissionnaire, ainsi que les contacts des personnes de références pour ces services rendus.



## C- OFFRE FINANCIERE

L'offre financière contient entre autres une proposition détaillée de prix, indiquant les valeurs en TTC selon le régime fiscal du soumissionnaire

## IV- CRITERES D'ATTRIBUTION DU MARCHE

*Le tableau ci-dessous décrit les critères d'évaluation des Offres :*

|          |  |
|----------|--|
| <b>A</b> | Pièces administratives. NB : Seules les pièces originales et copies certifiées conformes donneront droit au point dans cette partie.   |
| 1        | Une copie de cet avis d'appel à cotation entièrement paraphé sur toutes ses pages et signé à la dernière page par le prestataire ( <b>OUI ou NON</b> ) ;   |
| 2        | Attestation d'immatriculation au impôt de la société ou photocopie de la carte de contribuable ( <b>OUI ou NON</b> ) ;   |
| 3        | Attestation de non- redevance fiscale (en cours de validité) ( <b>critère éliminatoire pour cet appel d'offre</b> ) ;  |
| 4        | Copie Certifiée Conforme de l'expédition du Registre de commerce en lien avec l'objet du présent appel d'offre ( <b>Critère éliminatoire pour cet appel d'offre</b> )  |
| 5        | Attestation de domiciliation bancaire (datant de moins de 3 mois) ;( <b>OUI ou NON</b> )   |
| 6        | Un plan de localisation du bureau principal du soumissionnaire ;( <b>OUI ou NON</b> )  |
| <b>B</b> | <b>PIECES TECHNIQUES</b>   |
| 1        | Présentation de l'entreprise (historique, secteur d'activité, structure organisationnelle du soumissionnaire avec présentation du personnel clé) ; ( <b>si oui : 10, si non : 0</b> )  |
| 2        | Un exposé décrivant de manière explicite la compréhension des besoins exprimés par EGPAF ; ( <b>si oui : 15, si non : 0</b> )  |
| 3        | Méthodologie de recyclage dans la cas du réemploi et de destruction en tenant compte du volet environnemental et social du matériel informatique; ( <b>si oui : 40, si non : 0</b> ) ;   |
| 4        | La liste de toutes les personnes que le soumissionnaire compte faire intervenir dans la réalisation de la mission, ainsi que leurs CVs (Le prestataire indiquera le profil et l'expérience du personnel de la mission) ; ( <b>si oui : 15, si non : 0</b> )  |
| 5        | Des (04 ) procès verbaux de reception provisoires ou définitives de réalisation des travaux similaires réalisés par le soumissionnaire, ainsi que les contacts des personnes de références pour ces services rendus<br><br>( <b>si quatre (04) PV : 20 ; si trois (03) PV : 15 ; si deux (02) PV : 10; si autres : 0</b> ) |



**TOTAL NOTE TECHNIQUE /100 (*Toute note inférieure à 70 points est éliminatoire*)**

|          |  |
|----------|--|
| <b>C</b> | <b>Offre financière</b> ( <i>une note de l'offre technique inférieure à 70 points est non éligible pour l'offre financière</i> )                                   |
| 14       | Devis estimatif de la prestation : une proposition détaillée de prix, indiquant les valeurs en TTC selon le régime fiscal du soumissionnaire ( <b>OUI ou NON</b> ) |

## V-ANALYSE DES OFFRES

L'entreprise qui aura l'offre la plus petite et jugée raisonnable sera désignée '**MIEUX DISANTE**'

L'offre financière sera ainsi calculée :

**A- NOTE FINANCIERE = (offre la moins disante / Montant du challenger) X 100**

L'entreprise la moins disante dans ce cas possède la note financière de **100**.

**B- NOTE FINALE (ENTREPRISE LA MIEUX DISANTE)**

**NOTE FINALE :** (Note technique) x 70%+ (Note financière) x 30%

L'Entreprise ayant reçu la plus grande note sera considérée comme la **Mieux Disante** et se verra attribuer le marché.

### Évaluation financière

Les soumissions jugées techniquement conformes sont soumises à une vérification visant à déceler d'éventuelles erreurs arithmétiques dans les calculs et les totaux. Les erreurs sont corrigées par le comité d'évaluation de la manière suivante :

- Lorsqu'il y a une divergence entre le montant indiqué en chiffres et celui indiqué en toutes lettres, le montant en toutes lettres prévaut.
- Sauf pour les marchés à forfait, lorsqu'il y a une divergence entre un prix unitaire et le montant total obtenu en multipliant ce prix unitaire par la quantité, le prix unitaire indiqué prévaut.

Les montants ainsi corrigés sont opposables au soumissionnaire. Si ce dernier ne les accepte pas, son offre est rejetée.

## VI- LISTE DES MATERIELS DECLASSES PAR EGPAF

| Description   | Full Asset TAG     | Serial No  | Condition | Maintenance needed   |
|---|--------------------|------------|-----------|--|
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00200 | PF14M17P   | Damaged   | Faulty screen, no power; (Unreasonable maintenance cost)         |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00206 | MP1MAGEG   | Damaged   | Broken screen, Slit from body; (Unreasonable maintenance cost)   |
| Laptop HP PRO BOOK G2   | EGPAF.CA.ITE.01010 | CND51167QD | Damaged   | Faulty screen, no power; (Unreasonable maintenance cost)         |
| Laptop LENOVO X260  | EGPAF.CA.ITE.00523 | PC0K0FC9   | Damaged   | Faulty screen, no power; (Unreasonable maintenance cost)         |
| LENOVO X260 Laptop  | EGPAF.CA.ITE.00489 | PC0KETJ0   | Damaged   | Damaged MotherBoard; (Unreasonable maintenance cost)             |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00157 | MP1MABMB   | Damaged   | Damaged MotherBoard; (Unreasonable maintenance cost)             |
| Laptop LENOVO X260  | EGPAF.CA.ITE.01435 | PC0J5ZEN   | Damaged   | Damaged MotherBoard; (Unreasonable maintenance cost)             |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00035 | MP1MABSH   | Damaged   | Broken chassis, screen rotation; (Unreasonable maintenance cost) |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00080 | MP1MAGGG   | Damaged   | Broken chassis, screen rotation; (Unreasonable maintenance cost) |



|   |                    |                 |         |   |
|---|--------------------|-----------------|---------|---|
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00201 | PF14LZ4U        | Damaged | Faulty Motherboard; (Unreasonable maintenance cost)                   |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00156 | MP1MAGGB        | Damaged | Broken chasis, screen rotation; (Unreasonable maintenance cost)       |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00184 | PF14LV4Q        | Damaged | Broken chasis, screen rotation; (Unreasonable maintenance cost)       |
| LENOVO X260 Laptop  | EGPAF.CA.ITE.00880 | PC0K8REW        | Damaged | Faulty Motherboard; (Unreasonable maintenance cost)                   |
| Laptop HP Spectre X2 12-a009nr, Intel Core                      | EGPAF.CA.ITE.01309 | 5CD6428BCTC     | Damaged | Faulty Motherboard, No power; (Unreasonable maintenance cost)         |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB | EGPAF.CA.ITE.00188 | PF1RK1JL        | Damaged | Faulty Motherboard, Screen Rotation; (Unreasonable maintenance cost)  |
| MODEM WIFI LTE 4G+  | EGPAF.CA.ITE.01224 | XFJM21046121    | Damaged | Faulty batterie, broken power button; (Unreasonable maintenance cost) |
| MODEM WIFI Vodafone R216 4G                                     | EGPAF.CA.ITE.00070 | 325476894290.00 | Damaged | No power, Faulty battery; (Unreasonable maintenance cost)             |
| LENOVO X260 Laptop  | EGPAF.CA.ITE.00612 | PC0K8REB        | Damaged | Faulty Motherboard; (Unreasonable maintenance cost)                   |
| Voltage Stabilizer AF-AVR-3000 VA                               | EGPAF.CA.ITE.01183 | 20200501072     | Damaged | No power; (Unreasonable maintenance cost)                             |
| MODEM TP-Link 4G LTE WIFI M7200                                 | EGPAF.CA.ITE.01417 | 2221K8005514    | Damaged | Faulty charging circuit; (Unreasonable maintenance cost)              |



|  |                    |               |         |  |
|--|--------------------|---------------|---------|--|
| MOBILE D-LINK GSM 4 G LTE 200 mAh              | EGPAF.CA.ITE.00917 | TL1C108004935 | Damaged | Faulty charging circuit;<br>(Unreasonable maintenance cost)  |
| MODEM DLINK DWR 932C 4G LTE                    | EGPAF.CA.ITE.01170 | TL0Y111000648 | Damaged | Faulty charging circuit;<br>(Unreasonable maintenance cost)  |
| MOBILE D-LINK GSM 4 G LTE 200 mAh              | EGPAF.CA.ITE.00918 | TL1C107006652 | Damaged | Faulty charging circuit;<br>(Unreasonable maintenance cost)  |
| MODEM 4G LTE,D-LINK DWR-932                    | EGPAF.CA.ITE.01368 | TL1C114002456 | Damaged | Faulty charging circuit;<br>(Unreasonable maintenance cost)  |
| MOBILE D-LINK GSM 4G LTE 2000 mAh              | EGPAF.CA.ITE.00929 | TL1C105000631 | Damaged | Faulty charging circuit;<br>(Unreasonable maintenance cost)  |
| Internet Modem D-LINK DWR-M920                 | EGPAF.CA.ITE.01576 | U408122000740 | Damaged | Faulty charging circuit;<br>(Unreasonable maintenance cost)  |
| ROUTEUR ZYxEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00988 | S205333000460 | Damaged | No Network reception;<br>(Unreasonable maintenance cost)     |
| Laptop Computer HP 14-CF2226NIA                | EGPAF.CA.ITE.01125 | CND1279KFW    | Damaged | Faulty Motherboard;<br>(Unreasonable maintenance cost)       |
| Automatic AC Voltage Regulator 3000 VA         | EGPAF.CA.ITE.01062 | 2000003773    | Damaged | Faulty;(Unreasonable maintenance cost)                       |
| ROUTEUR ZYxEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00967 | S205333000552 | Damaged | Does not receive Network;<br>(Unreasonable maintenance cost) |
| ROUTEUR ZYxEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01243 | S215304002115 | Damaged | Does not receive Network;<br>(Unreasonable maintenance cost) |



|  |                    |               |         |   |
|--|--------------------|---------------|---------|---|
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00976 | S205333000562 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00971 | S205333000478 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01257 | S215304002098 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00962 | S205333000508 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01247 | S205346001302 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01245 | S205346001510 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01222 | S205346001458 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01239 | S205346001432 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00964 | S205333000625 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01244 | S205346001492 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00983 | S205333000506 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |



|  |                    |               |         |   |
|--|--------------------|---------------|---------|---|
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00975 | S195352001979 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01252 | S205346001511 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01213 | S215304000848 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00990 | S205333000515 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00963 | S205333000612 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00888 | S205319001557 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00970 | S205333000628 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01256 | S215304002099 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01240 | S205346001336 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00973 | S205333000525 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00978 | S205333000621 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |



|  |                    |               |         |   |
|--|--------------------|---------------|---------|---|
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00972 | S205333000458 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00994 | S205333000571 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00994 | S205333000571 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00985 | S205333000656 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00969 | S205333000535 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01235 | S205346001484 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01230 | S205346001586 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00987 | S205333000519 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00993 | S205333000558 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00980 | S205333000512 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00989 | S205333000409 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |



|  |                    |               |         |   |
|--|--------------------|---------------|---------|---|
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00982 | S205333000563 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00966 | S205333000592 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00992 | S205333000573 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01215 | S205346001303 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00981 | S205333000533 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01210 | S205346001334 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01249 | S215304001125 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01212 | S215304000850 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00965 | S205333000640 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01216 | S205346001454 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTEUR ZYXEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.01209 | S215304000846 | Damaged | Does not receive Network; (Unreasonable maintenance cost) |



|   |                    |                       |         |  |
|---|--------------------|-----------------------|---------|--|
| LENOVO NoteBook ThinkPad X280<br>20KECTOAWWRx | EGPAF.CA.ITE.00776 | PC16KF6J              | Damaged | Does not come on. Faulty motherboard;<br>(Unreasonable maintenance cost)             |
| LENOVO NoteBook ThinkPad X280<br>20KECTOAWWRx | EGPAF.CA.ITE.00356 | PC16KF6H              | Damaged | Does not come on. Faulty motherboard;<br>(Unreasonable maintenance cost)             |
| APC 650 VA Back-UPS                           | EGPAF.CA.ITE.00841 | 9B1810A15045          | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| APC 650 VA Back-UPS                           | EGPAF.CA.ITE.00602 | 9B1810A15056          | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| APC 650 VA Back-UPS                           | EGPAF.CA.ITE.00595 | 9B1726A11509          | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| APC 650 VA Back-UPS                           | EGPAF.CA.ITE.00600 | 9B1726A11521          | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| Back-UPS 650                                  | EGPAF.CA.ITE.00514 | 9B1712A0072           | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA              | EGPAF.CA.ITE.00718 | 410026816971204500024 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| SERVER UPS 1500 VA Back-up                    | EGPAF.CA.ITE.00450 | 3B1812X24543          | Damaged | Faulty Batteries.<br>Replacement could not be  |



|  |                    |              |         |  |
|--|--------------------|--------------|---------|--|
|  |                    |              |         | found; (Unreasonable maintenance cost)   |
| SERVER UPS 1500 VA Back-up                             | EGPAF.CA.ITE.00466 | 3B1812X22756 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| SERVER UPS 1500 VA Back-up                             | EGPAF.CA.ITE.00478 | 3B1812X23040 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| SERVER UPS 1500 VA Back-up                             | EGPAF.CA.ITE.00357 | 3B1812X24468 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| SERVER UPS 1500 VA Back-up                             | EGPAF.CA.ITE.00861 | 3B1812X24350 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| SERVER UPS 1500 VA Back-up                             | EGPAF.CA.ITE.00667 | 3B1812X22742 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS APC BVX Power Backup, Modele [BVX1600LI-GR], 230 V | EGPAF.CA.ITE.01049 | 9B2052A14493 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS APC BVX Power Backup, Modele [BVX22000], 230 V     | EGPAF.CA.ITE.01458 | 9B2143A14859 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS SERVER APC Back-UPS 1500VA                         | EGPAF.CA.ITE.01506 | 9B2208A03350 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |



|                                  |                    |                       |         |  |
|----------------------------------|--------------------|-----------------------|---------|--|
| UPS Server ECUS MPO-11500-1500VA | EGPAF.CA.ITE.00707 | 410026816971204000000 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA | EGPAF.CA.ITE.00717 | 410026816971204500038 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA | EGPAF.CA.ITE.00724 | 4100268168B1149400012 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA | EGPAF.CA.ITE.00719 | 4100268168B1149400018 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA | EGPAF.CA.ITE.00726 | 410026816971204500021 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA | EGPAF.CA.ITE.00699 | 4100268168B1149400012 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA | EGPAF.CA.ITE.00693 | 410026816971204500012 | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| APC 650 VA Back-UPS              | EGPAF.CA.ITE.00599 | 9B1726A11525          | Damaged | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA | EGPAF.CA.ITE.00694 | 10026816971204500039  | Damaged | Faulty Batteries.<br>Replacement could not be  |



|   |                    |                       |                |   |
|---|--------------------|-----------------------|----------------|---|
|   |                    |                       |                | found; (Unreasonable maintenance cost)  |
| UPS Server ECUS MPO-11500-1500VA                                  | EGPAF.CA.ITE.00698 | 410026816971204500021 | Damaged        | Faulty Batteries.<br>Replacement could not be found; (Unreasonable maintenance cost)  |
| Laptop HP, Intel Core i5-8265U, Windows 10 Professional X 64 Bits | EGPAF.CA.ITE.00024 | CND8334DQR            | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)                                   |
| MODEM WIFI Vodafone R216 4G                                       | EGPAF.CA.ITE.00072 | 320583782046          | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)                                   |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB   | EGPAF.CA.ITE.00102 | MP1MAJBT              | To Be Disposed | Damaged Hard drive and Faulty charging;<br>(Unreasonable maintenance cost)            |
| Laptop HP Pavilion X360, Convertible, Modèle 14-ba253cl           | EGPAF.CA.ITE.00140 | 8CG84139S7            | To Be Disposed | Damaged Hard drive and Faulty charging;<br>(Unreasonable maintenance cost)            |
| MODEM WIFI Vodafone R216 4G                                       | EGPAF.CA.ITE.00146 | 320876363196          | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)                                   |
| Laptop HP, Intel Core i5-8265U, Windows 10 Professional X 64 Bits | EGPAF.CA.ITE.00179 | 5CD9020C79            | To Be Disposed | Faulty Graphic card, Faulty battery, Broken chasis;(Unreasonable maintenance cost)    |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB   | EGPAF.CA.ITE.00222 | MP1MAJF9              | To Be Disposed | Faulty Graphic card, Faulty battery and Broken chasis;(Unreasonable maintenance cost) |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB   | EGPAF.CA.ITE.00241 | PF14MBYG              | To Be Disposed | Damaged Hard drive and Faulty   |



|  |                    |               |                |   |
|--|--------------------|---------------|----------------|---|
|  |                    |               |                | charging;(Unreasonable maintenance cost)                                |
| LENOVO X260 Laptop   | EGPAF.CA.ITE.00367 | PC0K8RED      | To Be Disposed | Damaged Hard drive and Faulty charging; (Unreasonable maintenance cost) |
| LENOVO X260 Laptop   | EGPAF.CA.ITE.00410 | PC0CNJD4      | To Be Disposed | Faulty Graphic card; (Unreasonable maintenance cost)                    |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB  | EGPAF.CA.ITE.00792 | MP1MABQ2      | To Be Disposed | Damaged Hard drive and Faulty charging; (Unreasonable maintenance cost) |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model S145-14IWL | EGPAF.CA.ITE.00810 | MP1MABM5      | To Be Disposed | Faulty Graphic card, Faulty battery; (Unreasonable maintenance cost)    |
| ROUTEUR DLIINK HSPA W/4X LAN 4G GSM                              | EGPAF.CA.ITE.00884 | RB111FC004689 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost)               |
| ROUTEUR ZYREL N300 4G LTE  | EGPAF.CA.ITE.00889 | S205319000140 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost)               |
| ROUTER ZYxEL N300 4G LTE (Slot SIM) DUAL BAND                    | EGPAF.CA.ITE.01221 | S205346001305 | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)                    |
| Desktop Monitor Think Vision T224I 23.8P                         | EGPAF.CA.ITE.01384 | VNA3P2HP      | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)                    |
| MODEM D-LINK GSM 4G LTE 2000 mAh                                 | EGPAF.CA.ITE.01385 | TL1C113004606 | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)                    |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model S145-14IWL | EGPAF.CA.ITE.01308 | PF152QFD      | To Be Disposed | Faulty Graphic card, Faulty battery; (Unreasonable maintenance cost)    |



|   |                    |               |                |   |
|---|--------------------|---------------|----------------|---|
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01253 | S205346001456 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01241 | S205346001513 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01238 | S205346001332 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01234 | S205346001512 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01233 | S205346001515 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01232 | S205346001519 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01229 | S205346001482 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01227 | S205346001356 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01220 | S205346001544 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| ROUTER ZYXEL N300 4G LTE (Slot SIM) DUAL BAND | EGPAF.CA.ITE.01172 | S215304001121 | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost) |
| MODEM INTERNET D-LINK GSM 4G LTE 2000mAh      | EGPAF.CA.ITE.01109 | TL1C113000277 | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)       |



|  |                    |                       |                |  |
|--|--------------------|-----------------------|----------------|--|
| ROUTEUR ZYREL N300 4G LTE                      | EGPAF.CA.ITE.01032 | S205319001275         | To Be Disposed | Does not receive Network;<br>(Unreasonable maintenance cost) |
| UPS Server ECUS MPO-11500-1500VA               | EGPAF.CA.ITE.01031 | 4100268168B1149400015 | To Be Disposed | No power, Faulty battery;(Unreasonable maintenance cost)     |
| ROUTEUR ZYxEL N300 4G LTE (slot SIM) DUAL BAND | EGPAF.CA.ITE.00979 | S205333000546         | To Be Disposed | Does not receive Network;<br>(Unreasonable maintenance cost) |
| Laptop HP ProBook 440 G8                       | EGPAF.CA.ITE.00951 | 5CD112GN52            | To Be Disposed | Does not receive Network;<br>(Unreasonable maintenance cost) |
| MOBILE D-LINK GSM 4 G LTE 200 mAh              | EGPAF.CA.ITE.00921 | TL1C107006666         | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)          |
| MOBILE D-LINK GSM 4 G LTE 200 mAh              | EGPAF.CA.ITE.00920 | TL1C107006645         | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)          |
| ROUTEUR ZYREL N300 4G LTE                      | EGPAF.CA.ITE.00902 | S195352001977         | To Be Disposed | Does not receive Network;<br>(Unreasonable maintenance cost) |
| ROUTEUR DLIINK HSPA W/4X LAN 4G GSM            | EGPAF.CA.ITE.00883 | TL0K103006432         | To Be Disposed | Does not receive Network;<br>(Unreasonable maintenance cost) |
| ROUTEUR DLIINK HSPA W/4X LAN 4G GSM            | EGPAF.CA.ITE.00882 | TL0K103006433         | To Be Disposed | Does not receive Network;<br>(Unreasonable maintenance cost) |
| MODEM DLINK 4G LTE WIFI DWR-932C               | EGPAF.CA.ITE.00867 | TLOY13001968          | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)          |
| MODEM DLINK 4G LTE WIFI DWR-932C               | EGPAF.CA.ITE.00863 | TLOY1J3001981         | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)          |



|  |                    |                       |                |   |
|--|--------------------|-----------------------|----------------|---|
| UPS Server ECUS MPO-11500-1500VA                                   | EGPAF.CA.ITE.00723 | 410026816971204500040 | To Be Disposed | No power, Faulty battery;(Unreasonable maintenance cost)                      |
| Canon Printer 1133A (F161600)                                      | EGPAF.CA.ITE.00637 | QXP28151              | To Be Disposed | Damaged MotherBoard;(Unreasonable maintenance cost)                           |
| UPS Server ECUS MPO-11500-1500VA                                   | EGPAF.CA.ITE.00597 | 410026816971204500016 | To Be Disposed | No power, Faulty battery;(Unreasonable maintenance cost)                      |
| Laptop LENOVO X270   | EGPAF.CA.ITE.00530 | PC0TTUU2              | To Be Disposed | Faulty Graphic card, Faulty battery;(Unreasonable maintenance cost)           |
| Laptop LENOVO X270   | EGPAF.CA.ITE.00438 | PC0TTUU3              | To Be Disposed | Faulty Graphic card, Faulty charging circuit; (Unreasonable maintenance cost) |
| Laptop DELL INSPIRON 5570N   | EGPAF.CA.ITE.00430 | DBYN142               | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)                          |
| Laptop LENOVO X270   | EGPAF.CA.ITE.00371 | PC0PD5XF              | To Be Disposed | Faulty Graphic card, Faulty battery;(Unreasonable maintenance cost)           |
| Laptop LENOVO Ideapad 330-15IKB, Intel Core i5, Model 130-14IKB    | EGPAF.CA.ITE.00236 | PF14M14A              | To Be Disposed | Damaged Hard drive and Faulty charging; (Unreasonable maintenance cost)       |
| Laptop HP, Intel Core i5-8265U, Windows 10 Professionnal X 64 Bits | EGPAF.CA.ITE.00217 | 8CG81914RW            | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)                          |
| Laptop HP, Intel Core i5-8265U, Windows 10 Professionnal X 64 Bits | EGPAF.CA.ITE.00149 | CND9202J8G            | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)                          |



|  |                    |                 |                |  |
|--|--------------------|-----------------|----------------|--|
| Laptop HP, Intel Core i5-8265U, Windows 10 Professional X 64 Bits          | EGPAF.CA.ITE.00148 | 8CG8200RPP      | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)           |
| Laptop HP, Pavilion Intel Core i5-8265U, Windows 10 Professional X 64 Bits | EGPAF.CA.ITE.00116 | 5CD9031KN1      | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)           |
| Laptop HP, Intel Core i5-8265U, Windows 10 Professional X 64 Bits          | EGPAF.CA.ITE.00112 | 8CG842CV5C      | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)           |
| Laptop HP, Intel Core i5-8265U, Windows 10 Professional X 64 Bits          | EGPAF.CA.ITE.00111 | 8CG84924VS      | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)           |
| Laptop HP, Intel Core i5-8265U, Windows 10 Professional X 64 Bits          | EGPAF.CA.ITE.00110 | 8CG819484S      | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)           |
| Laptop HP Pavilion X360, Convertible, Modèle 14-ba253cl                    | EGPAF.CA.ITE.00107 | 8CG82436DX      | To Be Disposed | Damaged MotherBoard; (Unreasonable maintenance cost)           |
| MODEM WIFI Vodafone R216 4G  | EGPAF.CA.ITE.00076 | 320583781899    | To Be Disposed | Does not receive Network; (Unreasonable maintenance cost)      |
| Mobile Phone HUAWEY T-5  | EGPAF.CA.COM.00136 | RZ8RC20H8FE     | To Be Disposed | Faulty screen, Faulty battery; (Unreasonable maintenance cost) |
| Mobile Phone Alcatel 1S  | EGPAF.CA.COM.00120 | RPND09BOJIE00UK | To Be Disposed | Faulty screen, Faulty battery; (Unreasonable maintenance cost) |
| Mobile Phone SAMSUNG GALAXY A03s Blue                                      | EGPAF.CA.COM.00107 | R9HR80HT6ZH     | To Be Disposed | Faulty screen, Faulty battery; (Unreasonable maintenance cost) |



**Elizabeth Glaser  
Pediatric AIDS Foundation**  
Fighting for an AIDS-free generation